cs3310/v02/v03 XLR connection
=============================

On A Board
-if you only have 1 XLR input , just pick any inputs in the A board as XLR in
-Left + connect L1, Right + connect R1,
-Output side L Out, will be Left channel +
-Ouput side ROut, will be Right channel +

On B board
-Pick the same input channel as XLR negative signal
-Left channel - connect L1, Right Channel - connect R1
-then you have LOut output as Left channel - phase
-ROut as Right channel - phase

-if you have more than on XLR input, just use the same method above to connect other input signal

DIYGene